


## Watermain Breaks by Type



The majority of watermain breaks occur on cast iron pipes. Cast iron is being replaced by PVC and we are seeing fewer breaks each year.